

TECHNICAL NOTE

DATE:	21 August 2026	CONFIDENTIALITY:	Public
SUBJECT:	Site Monitoring Report – August 2026		
PROJECT:	Swanage Town Council – Shore Road	AUTHOR:	Sam Horner
REVIEWER:	Ben Ward	APPROVER:	David Roy

1 INTRODUCTION

- 1.1 WSP UK Ltd (WSP) was commissioned by Swanage Town Council (STC), ‘the Client’, to produce a supplementary technical note detailing the findings of a follow up defect walkover survey undertaken in August 2026. Areas of ground and retaining wall instability have been identified across the site over a number of years. It is not known when these defects were first identified by STC.
- 1.2 An initial defect survey was undertaken in June 2023, with a subsequent site monitoring report issued, providing a baseline list of defects identified across the site (1). These risks were assigned a risk rating using a qualitative risk assessment methodology.
- 1.3 A description of the site locale and references to existing geotechnical information are presented within Section 1 of the Ground Stabilisation Feasibility Study (2).
- 1.4 References to supplementary information relating to buried services, UXO risk and topographical surveys are provided in Table 1 of the Ground Stabilisation Options Refinement Technical Note (3).

2 DEFECT WALKOVER SURVEY

SHORE ROAD AREA

- 2.1 The latest defect walkover survey was undertaken on the 4th August 2026, by a WSP Geotechnical Engineer. On the date of the inspection weather conditions were dry and sunny.
- 2.2 The purpose of the walkover was to record the updated condition of defects identified during the initial defect survey in June 2023 (1), interim inspections undertaken in October 2023 (4), February 2024 (5), May 2024 (6), October 2024 (7), February 2025 (8), June 2025 (9), October 2025 (10), February 2026 (11) and the latest survey in completed in August 2026.
- 2.3 Information on any new defects which may have developed in the interim period were also documented.
- 2.4 Photos and measurements of each defect were taken and compared to the previous survey in order to determine the rate of deterioration of assets across the site. This would inform the revised risk rating assigned to each defect within the defect schedule.
- 2.5 The walkover survey comprised inspection of the following areas:
 - The Spa;
 - The Spa Beach Huts;
 - Weather Station Field; and
 - Sandpit Field.
- 2.6 Defect areas were categorised by location with the Spa and Spa Beach Hut areas denoted “A”, Weather Station Field denoted “B”, and Sandpit Field denoted “C”, in the defect schedule. The defect schedule is presented as Appendix A of this technical note.

- 2.7 A total of 57 no. defects were identified during the site walkover (1 additional to the previous visit – See defect schedule item A24). These typically related to, but not limited to the following:
- Retaining walls with vertical and/or horizontal cracking, bulging or bowing, excessive settlement or leaning;
 - Hummocky areas where surface distress was identified in grassed areas and footways;
 - Tension cracking forming in over steep vegetated slopes;
 - Footway and stairway distress in the form of tension cracking, structural cracking, pavement settlement and heave; and
 - Dilapidated surface drainage and retaining wall weepholes, blocked or semi-blocked by debris and siltation.
- 2.8 Of the 57 no. defects observed during the walkover survey, 49 no. related to retaining walls, 5 no. related to pavements and footways, 2 no. related to earthwork slopes, and 1 no. related to drainage systems.
- 2.9 Where identified, a characteristic image of each defect has been included within the defect schedule.
- 2.10 A link to a repository of images captured during the inspection shall be made available on request.
- 2.11 An updated defect risk rating has been assigned to each of the defects based on the August 2026 site walkover, presented in the defect schedule (see Appendix A). These values have been assigned based on a qualitative risk assessment (QRA), to give an approximation of risk levels at the time of the survey.
- 2.12 The QRA methodology used to derive defect risk ratings is presented as Appendix B.
- 2.13 Further information on these defects is presented within the defect schedule. The risk level from the previous surveys has been presented within the defect schedule to highlight changes in asset condition over time.
- 2.14 Recommendations on defects which require additional intervention measures are detailed within Section 4.

GUN EMPLACEMENT

- 2.15 During the August 2026 walkover the Client requested the WSP engineer inspect the gun emplacement with a focus on the settlement observed from the surface. The Client removed the boarding on the side of the tunnel previously placed to cover voiding observed in April 2025.
- 2.16 The layout of the gun emplacement consists of a front room (historical location of the gun), a staff room, and a storage room, connected to the front room with a tunnel. The front room and the staff room appeared in good condition during the visit.
- 2.17 The tunnel connecting the front room consists of a single skin masonry wall supporting a concrete slab on top. The walls are approximately 2m high and set below the natural ground level for their most part, however the top portion of the wall is underneath backfill, believed to be placed as part of the original construction.
- 2.18 The two tunnel walls were both noted to be leaning, with the northern wall leaning at approximately 12° and resting on the southern wall. The front wall is providing no support to the above slab, and halfway along its length it appears to be leaning in the other direction, with the toe of the wall believed to have kicked out into the centre of the tunnel. See Figure 1.
- 2.19 The southern tunnel wall is also leaning into the tunnel, with its outside edge providing a partial support for the roof slab sporadically along its length. The material behind this rear wall was observed to have slightly subsided and the steps for the roof viewpoint access can also be observed to be settling towards the rear of the wall. This is likely a result of the loss of support from the wall. See Figure 2.

- 2.20 A structural report suggests the roof slab is not attached to the front room and is just cast in situ up against it, and as a result of the damaged to the walls it is believed that this friction between the front room and the slab and its joint to the ammo room at the rear are the only locations of support to the slab.
- 2.21 The storage room at the rear is buried under an earth mound, hence the condition of the walls cannot be commented on. The mound shows significant desiccation cracks and tension cracks along its lengths. These were observed in previous inspections. See Figure 3.
- 2.22 For further information relating to this defect see item C18 in the defect schedule and the recommendations in Section 4.



Figure 1:a) Voiding created by damaged wall. Looking into front room. b) Displaced northern wall, showing it leaning on the southern wall



Figure 2:a) Subsidence behind the tunnel. b) Staff room showing depth of rooms below ground level.



Figure 3: Desiccation and tension cracking in earth placed on top of ammo room

LAND TO REAR OF SEA BREEZE RESTAURANT

- 2.23 A visual inspection of the land to the rear of the Sea Breeze Restaurant and Swanage Visitors Centre was undertaken on 4th August 2026, as part of the Shore Road inspection works.
- 2.24 Previous visual inspections of the area were undertaken in October 2023, February 2023, May 2024, October 2024, February 2025, June 2025, October 2025 and February 2026. Photographic records of observations collected can be made available on Client request.
- 2.25 From the period between February 2026 and August 2026, no significant change was observed in the condition of the slope, retaining wall and rear structure walls. It should be noted that the slope was covered in grass making a visual survey difficult.

3 MONITORING DATA

PREVIOUS SURVEYS AND INTERPRETATION (JUNE 2021 – AUGUST 2026)

- 3.1 Information regarding the geotechnical monitoring regime at the site is provided within the 2021 Geotechnical Assessment Report produced by South West Geotechnical (SWG) Ltd (10).
- 3.2 For information regarding previous survey data and interpretation for the period of June 2021 to May 2024, refer to the May 2024 Site Monitoring Report (6).
- 3.3 For information regarding the survey and monitoring period May to September 2024, refer to the October 2024 Site Monitoring Report (7).
- 3.4 For information regarding the survey and monitoring period October 2024 to January 2025, refer to the February 2025 Site Monitoring Report (9).
- 3.5 For information regarding the survey and monitoring period January 2025 to July 2025, refer to the June 2025 Site Monitoring Report (9).
- 3.6 For Information regarding the survey and monitoring period July 2025 to November 2025, refer to the October 2025 Site Monitoring Report (10).
- 3.7 For Information regarding the survey and monitoring period November 2025 to February 2026, refer to the February 2026 Site Monitoring Report (11).

SURVEY PERIOD (FEBRUARY 2026 – AUGUST 2026)

- 3.8 Since February 2026 2 further monitoring rounds were undertaken in March and July.
- 3.9 Where Face A and Face B have been described below, the following definitions should be noted:
- Face A – Movement in the direction of the principal axis, with positive values relating to movements in the parallel to the direction of the downslope; and
 - Face B – Movement perpendicular to the direction of the principal axis, with positive values relating to movements bearing 90 degrees to positive Face A readings, in the direction of perpendicular to the downslope.
- 3.10 The following points of note were observed in the latest round of inclinometer data:
- BH01 – Inclinometer
- 3.11 In the Face A orientation, no significant movement was recorded with the maximum displacement decreasing by approximately 3.1mm since February 2026.
- 3.12 The deflection recorded in July 2026 reflect a recovery in displacement from the previously recorded maximums.

- 3.13 The values in the Face B direction have not significantly changed. During the monitoring period a displacement of -5.2mm was recorded however that recovered by the final monitoring round to values similar to those previously recorded.
- 3.14 The increase in the Face A direction was reviewed, although movement is still ongoing the values are not yet significant and should be reviewed again after the next monitoring rounds.

BH03 – Inclinator

- 3.15 In the Face A orientation, the increase measurements previously recorded slightly recovered, by a value of 3.1mm, with the final measurement recorded being 18.4mm.
- 3.16 In the Face B orientation the increase observed during the previous monitoring phase has reduced, with a decrease of 4.4mm recorded. Movement was shown in the upper 1.5m however the movement reduced with depth. The values measured in this inclinometer are within the maximum values recorded.
- 3.17 The previous monitoring report referred to ongoing movement in Face A, this appears to no longer be increasing with a slight recovery in the measurements. This should be reviewed after the next rounds of monitoring data.

BH06 – Inclinator

- 3.18 The ongoing movement observed in the February 2026 monitoring review in the Face A direction have halted. The maximum value reached, 3.3mm in January 2026, was the maximum it reached before deflections recovered. The value recorded in July 2026 was -3.5mm, a displacement of -6.8mm since January. This trend of deflection and recovery is not uncommon across the site and should be reviewed after the next rounds of monitoring results.
- 3.19 In the Face B orientation, the previously recorded displacement of 3.2mm was recovered to -3.5mm. The measurements in this period showed minor fluctuations in the values however these were all minor differences.

BH07 – Inclinator

- 3.20 In the Face A orientation, an increased deflection of 0.5mm was observed between February 2026 and July 2026. The maximum deflection observed was at 0.5m below ground level.
- 3.21 In the Face B orientation the recovery in deflections measured continued until March 2026 with a total recovery of 1.1mm since February 2026. The measurement in July 2026 however showed a significant increase of 6.5mm from the March reading at 0.5m below ground level. This is the largest deflection measured during the monitoring history at this location. After the next round of monitoring this should be reviewed to determine as to whether this is an outlier or reflects true slope movement.
- 3.22 The overall trend in the face A direction continues to show an increase in deflection over the last year of monitoring indicating a trend of downward slope movement. This creep appears to be continuing however the rate of movement has slowed since the last monitoring review. This data should be continually reviewed to determine whether this rate of downward slope movement is continuing.
- 3.23 Despite these increases no significant change in asset condition for the defects in the vicinity of BH07, namely B2, B3, and B4 was observed.

BH10 – Inclinator

- 3.24 In the Face A direction the increase in displacement previously observed stopped in February 2026 before recovering by a total of 5.8mm by the July measurement. This displacement was observed between 2m and 1.5m bgl.

- 3.25 In the Face B direction a small increase of 0.7mm was observed between the February 2026 and July 2026 readings. These readings still indicate a lower displacement than the results recorded between October and December in 2025.
- 3.26 There should be a continued review of the monitoring data for this inclinometer to check the pattern of increased deflection and recovery continues and that deflections do not just keep increasing.
- 3.27 This inclinometer is located to the south of the gun emplacement. Although no significant change has been noted in the inclinometer there has been a change in condition of the gun emplacement. Comments on the condition of this are included in Section 4.

BH12 – Inclinometer

- 3.28 In the Face A direction measurements increased to a maximum value of 10.7mm in March 2026 in line with the previous measurements. This displacement had recovered to 5.4mm (at 0.5m bgl.) in the July 2026 recording.
- 3.29 In the Face B direction the previous recovery observed up to February 2026 halted and an increase in deflection to 4.5mm was observed in the July 2026 reading, an increase of 6.7mm over this period. There should be a continued review of the monitoring data for this inclinometer to check the pattern of increased deflection and recovery continues and that deflections do not just keep increasing.

BH014 – Inclinometer

- 3.30 No significant movement was observed in the inclinometers between February 2026 and August 2026.

BH016 – Inclinometer

- 3.31 No significant movement was observed in the inclinometers between February 2026 and August 2026. A small increase of 1.5mm was observed in the Face A direction, however the final in this direction was -0.3mm hence it is likely following the general trend of increased deflection followed by recovery.

GROUNDWATER MONITORING

- 3.32 During the return visits to monitor the inclinometers the groundwater levels are also recorded where boreholes are installed.
- 3.33 In the period between February 2026 and August 2026 the groundwater monitoring showed lower values than previous period. This likely reflects the dry weather and below average rainfall for the current time of year.




Figure 4: Groundwater monitoring data

- 3.34 The previous site walkover noted significant seepage from walls and heavy saturation underfoot in the flat grassy areas. None of these findings were observed during the August 2026 walkover, with the ground being significantly dry showing signs of desiccation. During the lead up to this monitoring visit a significant dry and hot spell had occurred, likely contributing to the low groundwater.
- 3.35 At the time of writing the Environment Agency has declared the area to be in 'drought conditions', these conditions were reflected in the site observations and the groundwater monitoring.

RECOMMENDATIONS

- 3.36 It is recommended that groundwater and inclinometer monitoring is continued alongside periodic site walkovers to ensure that site defects are appropriately risk managed, and areas cordoned off as necessary.

4 RECOMMENDATIONS

SHORE ROAD AREA

- 4.1 Following review of the latest defect survey and the monitoring information, the following general recommendations are given:
- Ongoing walkover surveys should be undertaken at regular intervals (i.e. three to four monthly), to assess the condition of defects identified, and any new defects which have since developed;
 - After periods of heavy and prolonged rainfall, an inspection of listed defects should be undertaken by a suitability qualified person on behalf of the Client, to ensure all areas are still sufficiently safe to be opened to members of the public;

- Areas identified as having high risk (risk rating equal to or greater than 9), should be visually inspected weekly, or after periods of heavy and prolonged rainfall, to ensure no rapid deterioration in the asset has occurred; and
- Exclusion zones that are currently installed across the survey area should continue to be monitored and maintained.

4.2 Based on the revised defect risk ratings, recommendations for revised defect specific mitigation measures are presented in Table 1. These are in line with previous recommendations.

4.3 Further detail is provided within the Defect Schedule, presented as Appendix A.

GUN EMPLACEMENT

4.4 Following review of the information obtained from the walkover the following recommendations are given:

- Ongoing walkover surveys should be undertaken at regular intervals (i.e. three to four monthly), to assess the condition of the area and identify any significant changes;
- An exclusion zone should be installed around the tunnel, back room, and viewpoint steps. This shall prevent public access to the immediate areas at risk; and
- During subsequent monitoring visits the area at the front of the gun emplacement with the bench should be reviewed to determine if this is still safe to remain open to the public.

LAND TO REAR OF SEA BREEZE RESTAURANT

4.5 No significant change in condition of slope, wall or building structures was observed in the latest walkover survey.

4.6 It is recommended that monitoring and continued visual inspection of this area is undertaken as part of the wider Shore Road works, to assess the condition of the associated assets over time.

Table 1 – Recommended Defect Mitigation Measures

Defect Ref.	Defect Location	Defect Photo	Recommended Mitigation Measure
A18	Spa Beach Huts		- Continue to monitor after significant rainfall events. - Maintain the closure in the grassy area below the wall. - If further movement or signs of deterioration continue to develop, consider restricting car parking on the south bound section of road adjacent to the asset. - Ongoing patch repairs to help manage risk to public from cracking/ trip hazards, subject to review of any increasing in cracking.
B11	Weather Station Field	 	- Maintain exclusion zone around defect. - Continue to monitor regularly (weekly), or after significant rainfall events. - If the defect is observed to propagate further laterally (outwards east or west along Walrond Road), extend the exclusion zone to capture any further at risk areas.


Defect Ref.	Defect Location	Defect Photo	Recommended Mitigation Measure
C12	Sandpit Field		Continue to monitor propagation of tension cracks to the rear of recently planted area (previous bench locations).
C18	Sandpit Field		- Access to roof and area above gun emplacement to be fenced off to members of the public. - Continued monitoring to be undertaken to check deterioration of the existing defect area. - Ongoing monitoring to assess the areas around the gun emplacement not fenced off to determine any change in their condition.


REFERENCES



1. **WSP UK Ltd.** *Site Monitoring Report - Shore Road (June 2023)*. Bristol, UK : WSP, 2023.
2. —. *Swanage Seafront - Ground Stabilisation Feasibility Study (Report No. 70094760-GEO-REV001)*. Bristol, UK : WSP UK Ltd, 2022.
3. —. *Swanage TC - Shore Road - Ground Stabilisation Options Refinement Technical Note – Hybrid Option*. Bristol, UK : WSP, 2023.
4. —. *Site Monitoring Report - Shore Road (October 2023)*. Bristol, UK : WSP, 2023.
5. —. *Site Monitoring Report - Shore Road (February 2024)*. Bristol, UK : WSP, 2024.
6. —. *Site Monitoring Report - Shore Road (May 2024)*. Bristol, UK : WSP, 2024.
7. —. *Site Monitoring Report - Shore Road (October 2024)*. Bristol, UK : WSP, 2024.
8. —. *Site Monitoring Report - Shore Road (February 2025)*. Bristol, UK : WSP, 2025.
9. —. *Site Monitoring Report - Shore Road (June 2025)*. Bristol, UK : WSP, 2025.
10. —. *Site Monitoring Report - Shore Road (October 2025)*. Bristol, UK : WSP UK Ltd, 2025.
11. **South West Geotechnical Ltd.** *Swanage Seafront - Geotechnical Assessment (Report No. 12660)*. Devon, UK : South West Geotechnical, 2021.





APPENDIX A – DEFECTS SCHEDULE

Swanage Town Council - Shore Road - Asset Defect Schedule (February 2026)																February 2026 Risk Rating	August 2026 Risk Rating					
Defect Ref.	Defect Location	Easting (m)	Northing (m)	Sample Photo of Defect	Initial Defect Description (June 2023)	Defect Description (Oct 2023)	Defect Description (Feb 2024)	Defect Description (May 2024)	Defect Description (October 2024)	Defect Description (February 2025)	Defect Description (June 2025)	Defect Description (October 2025)	Defect Description (February 2026)	Defect Description (August 2026)	Risk Level	Likelihood (Number)	Likelihood	Effect (Number)	Effect	Risk Level (Number)	Risk Level	
A1	The Spa	403068	79415		Vertical and horizontal cracking, bulging/horizontal sliding of failing wall section. Crack width 10 - 20mm. Bowing of wall face, up to 40mm. Loose blockwork, missing masonry, loss of mortar between blockwork. Crack length 1.2m wall height 1.2m Retained height 3.0m+.	Crack width increased to 25mm. Bowing of wall face up to 50mm. North facing wall completely sheared from east facing return. Additional bowing/shearing of masonry at bench level adjacent to return wall, with up to 70mm movement. Recommended that area is fenced/closed off. Return wall supports 3.5m of backfill. In the event of total failure, potential to cause significant harm to members of the public.	No significant change Note heras fencing present to separate area from public	No significant change	No significant change	No significant change	No significant change. As noted in 2024, Heras fencing prevents measurement of the cracks.	No significant change. As noted in 2024, Heras fencing prevents measurement of the cracks.	No significant change. As noted in 2024, Heras fencing prevents measurement of the cracks.	No significant change. As noted in 2024, Heras fencing prevents measurement of the cracks.	High	3	Likely	3	High	9	High	
A2	The Spa	403068	79423		Retaining wall height: 1.3m Retained height: 1.3m Horizontal cracking, crack width up to 10mm. Cracking along failed mortar joint.	Max crack width increased 15mm. Otherwise no significant change (NSC) observed.	No significant change	Slight increase in crack width observed. Otherwise, no significant change.	Max crack width increased from 15mm to approx. 17mm. Otherwise no significant change.	No significant change	No major change in crack width - approx. 15 - 17mm. Length of crack 1.5m Mortar render debonding from the wall.	No significant change.	No significant change. Seepage was observed from the crack towards the upper steps, water was trickling down the steps.	No significant change. Crack width measured - approx 15-20mm. No seepage observed.	Low	2	Unlikely	1	Very Low	2	Low	
A3	The Spa	403061	79407		Retaining wall height: 0.8m Retained height: 0.8m Vertical cracking and horizontal displacement of wall. Crack width, 40 - 60mm with loose and missing masonry. Evidence of previous repair attempt with cement mix.	Max crack width 80mm. Max translational movement of masonry (left and right hand side) 50mm. Otherwise no significant change, and low risk.	No significant change	No significant change	Loose masonry to the touch observed. No significant change.	No significant change	Max crack width still approx. 80mm. Max translational movement of masonry (left and right hand side) increased to 55mm from last recorded measurement in October 2023. Cracking also observed on the east end of the bench. Length 0.7m Width 50mm. Retaining wall at the east 1.2m height, depth 0.5m.	No significant change Max crack width still approx. 80mm. Max translational movement of masonry (left and right hand side) increased to 55mm from last recorded measurement in October 2023. Cracking observed on the adjacent bench - east end. Width 50mm.	No significant change Max crack width still approx. 80mm. Max translational movement of masonry (left and right hand side) still at 55mm. Cracking observed on the adjacent bench - east end. Width up to 50mm.	No significant change Max crack width still approx. 80mm on the left, and 80-90mm on the right. Max translational movement of masonry (left and right hand side) still at 55mm. Cracking on the adjacent bench still have a width up to 50mm.	Low	2	Unlikely	1	Very Low	2	Low	



Swanage Town Council - Shore Road - Asset Defect Schedule (February 2026)															February 2026 Risk Rating	August 2026 Risk Rating					
Defect Ref.	Defect Location	Easting (m)	Northing (m)	Sample Photo of Defect	Initial Defect Description (June 2023)	Defect Description (Oct 2023)	Defect Description (Feb 2024)	Defect Description (May 2024)	Defect Description (October 2024)	Defect Description (February 2025)	Defect Description (June 2025)	Defect Description (October 2025)	Defect Description (February 2026)	Defect Description (August 2026)	Risk Level	Likelihood (Number)	Likelihood	Effect (Number)	Effect	Risk Level (Number)	Risk Level
A4	The Spa	403060	79395		Retaining wall height: 1.0m Retained height: 1.0m Vertical cracking, width up to 30mm. No bowing/bulging of wall face observed. Pavement cracking at base of retaining wall mirroring cracking in retaining wall face.	Surveyed - No significant change.	Vertical cracking, width 40mm	No significant change	No significant change	No significant change	No significant change.	No significant change. Crack width is 30 - 40mm.	No significant change. Crack width is still 30 - 40mm.	No significant change. Crack width is still 30 - 40mm.	Low	1	Negligible	1	Very Low	1	Low
A5	The Spa	403051	79400		Retaining wall height: 0.9m Retained height: 0.2m Vertical and horizontal cracking, crack width up to 30mm. Appears lower section of wall has settled/rotated away from top section, causing failure of mortar joint and cracking in wall.	Surveyed - No significant change.	No significant change	No significant change	Repair to the mortar joints has been made since the last inspection. Risk of failure significantly reduced, however recommended to monitor asset condition in future surveys to ensure repair remains serviceable.	No significant change. Repair has held.	No significant change to the rear face of the wall - repair still holding. Front face of the wall has a crack running from a block below the base of the repair to the ground. Width ranging between 10 - 30mm. Render loose.	No significant change.	No significant change on front or rear faces. A small amount of debonding was noticed between the wall and the repair observed in October 2024.	No significant change on front or rear faces. A small amount of debonding was noticed between the wall and the repair observed in October 2024. Dessication was observed at the toe of the defect in the grass slope. Cracks opened up between the toe of the wall and the ground.	Low	1	Negligible	1	Very Low	1	Low
A6	The Spa	403060	79402		Retaining wall height: 0.9m Retained height: 0.9m Vertical cracking, crack width up to 20mm. Horizontal displacement of right side of wall 10mm from left side. Evidence of previous mortar joint repair, which has since re-failed.	Horizontal displacement of right side of wall increased to 15mm. Otherwise, no significant change, and low risk.	No significant change	No significant change	Horizontal displacement has increased in areas to a max. of 60mm. No significant change in risk profile for asset.	No significant change	No significant change.	No significant change.	No significant change. Crack still measured a max width of 60mm.	No significant change. Overhang width now 70mm.	Low	2	Unlikely	1	Very Low	2	Low
A7	The Spa	403058	79400		Pavement cracking and uneven ground. Differential settlement/transverse cracking in pavement with height up to 10mm. Longitudinal cracking, with width up to 2mm.	Surveyed - No significant change.	No significant change	Differential settlement/transverse cracking in pavement increased from 10mm to 30mm. No significant change to risk rating.	Differential settlement in pavement at maximum, increased from 30mm to 35mm. No significant change in asset risk. <i>Note: Extreme south sloping of pavement in this area, consider risk to pedestrians if this becomes more pronounced.</i>	No significant change	No significant change. Sloping of pavement to the south. See comment from October 2024.	No significant change.	Differential settlement in pavement still approx 30mm. Longitudinal cracking between the pavement and the upper slope wall up to 20mm in width. Where this has been previously repaired / grouted cracking / debonding has been observed and settlement of repaired areas has been noted. Cracks up to 130mm in width. Approximately 10° cross fall in the pavement.	Low	3	Likely	2	Low	6	Medium	

Swanage Town Council - Shore Road - Asset Defect Schedule (February 2026)															February 2026 Risk Rating	August 2026 Risk Rating					
Defect Ref.	Defect Location	Easting (m)	Northing (m)	Sample Photo of Defect	Initial Defect Description (June 2023)	Defect Description (Oct 2023)	Defect Description (Feb 2024)	Defect Description (May 2024)	Defect Description (October 2024)	Defect Description (February 2025)	Defect Description (June 2025)	Defect Description (October 2025)	Defect Description (February 2026)	Defect Description (August 2026)	Risk Level	Likelihood (Number)	Likelihood	Effect (Number)	Effect	Risk Level (Number)	Risk Level
A8	The Spa	403052	79390		Retaining wall height: 1.0m Retained height: 1.0m Vertical and horizontal cracking, cracking width 30 - 60mm. Length of defect 0.7m. Evidence of minor previous patch repairs with cement mix.	No bowing observed. Surveyed - No significant change.	No significant change At end of wall vertical cracking noted 10-20mm in width	No significant change	Length of defect increased from 0.7m to 0.95m. No significant change in asset condition or risk rating.	No significant change	Length of defect increased to 1.2m. Crack width still approximately 60mm max. No significant change in asset condition or risk rating.	No increase in defect length. No significant change in asset condition or risk rating.	No increase in defect length. Cracking ranges from 20 - 70mm. No significant change in asset condition or risk rating.	No increase in defect length. Cracking ranges from 20 - 70mm. No significant change in asset condition or risk rating.	Low	2	Unlikely	1	Very Low	2	Low
A9	Spa Beach Huts	403028	79367		Retaining wall height: 0.9m Retained height: 0.9m Minor vertical cracking, missing masonry blocks and silted up and damaged back of wall drainage. Damage potentially due to running services through wall, post wall construction.	Surveyed - No significant change.	No significant change	No significant change	No significant change	No significant change	No significant change.	No significant change.	No significant change.	No significant change.	Low	2	Unlikely	1	Very Low	2	Low
A10	Spa Beach Huts	403054	79358		Retaining wall height: 1.25m Retained height: 1.25m Vertical cracking, crack height 0.9m, crack width up to 30mm. Damaged weephole / void at the base of the wall (see left of survey book).	Surveyed - No significant change.	No significant change	No significant change	No significant change	No significant change	No significant change.	Crack width up to 30mm. No significant change.	Crack width up to 30mm. No significant change.	Crack width up to 30mm. No significant change.	Low	2	Unlikely	2	Low	4	Low
A11	Spa Beach Huts	403042	79361		Retaining wall height: 2.15m Retained height 2.15m Hairline vertical cracking full height of the wall, crack width ~1mm. Weephole silted up and 2/3 blocked by additional concrete pours, potential from previous remedial works.	Could not survey due to lack of access to mid-terrace. From visual inspection in accessible location, no significant change observed.	No significant change	No significant change Could not survey due to lack of access to mid-terrace. From visual inspection in accessible location, no significant change observed.	Could not survey due to lack of access to mid-terrace. From visual inspection in accessible location, no significant change observed.	Could not survey due to lack of access to mid-terrace. From visual inspection in accessible location, no significant change observed.	Could not survey due to lack of access to mid-terrace. From visual inspection in accessible location, no significant change observed.	Could not survey due to lack of access to mid-terrace. From visual inspection in accessible location, no significant change observed.	Could not survey due to lack of access to mid-terrace. From visual inspection in accessible location, no significant change observed. Board blocking covered area next to defect has been broken / removed. Likely for public access - cigarette butts noted.	Could not survey due to lack of access to mid-terrace. From visual inspection in accessible location, no significant change observed. Board blocking covered area next to defect has been replaced since October 2025 inspection.	Low	1	Negligible	3	High	3	Low


Swanage Town Council - Shore Road - Asset Defect Schedule (February 2026)															February 2026 Risk Rating	August 2026 Risk Rating					
Defect Ref.	Defect Location	Easting (m)	Northing (m)	Sample Photo of Defect	Initial Defect Description (June 2023)	Defect Description (Oct 2023)	Defect Description (Feb 2024)	Defect Description (May 2024)	Defect Description (October 2024)	Defect Description (February 2025)	Defect Description (June 2025)	Defect Description (October 2025)	Defect Description (February 2026)	Defect Description (August 2026)	Risk Level	Likelihood (Number)	Likelihood	Effect (Number)	Effect	Risk Level (Number)	Risk Level
A12	Spa Beach Huts	403050	79369		Dilapidated aco surface water drainage system. Drainage gratings broken, and invert fully silted up for the full length of the retaining wall.	Could not survey due to lack of access to mid-terrace. From visual inspection in accessible location, no significant change observed.	No significant change	No significant change Could not survey due to lack of access to mid-terrace. From visual inspection in accessible location, no significant change observed.	Could not survey due to lack of access to mid-terrace. From visual inspection in accessible location, no significant change observed.	Could not survey due to lack of access to mid-terrace. From visual inspection in accessible location, no significant change observed.	Could not survey due to lack of access to mid-terrace. From visual inspection in accessible location, no significant change observed.	Could not survey due to no access to mid-terrace. From visual inspection in accessible location, no significant change observed.	Could not survey due to no access to mid-terrace. From visual inspection in accessible location, no significant change observed.	Could not survey due to no access to mid-terrace. From visual inspection in accessible location, no significant change observed.	Low	3	Likely	1	Very Low	3	Low
A13	Spa Beach Huts	403055	79380		Retaining wall height: 2.15m Retained height: 2.5m Horizontal hairline cracking, crack width 1mm. Cracking located 1.85m from existing ground level. Slight bulging/bowing at the mid span/mid height of retaining wall. Defect length: 8m.	Could not survey due to lack of access to mid-terrace. From visual inspection in accessible location, no significant change observed.	No significant change	No significant change. Could not survey due to lack of access to mid-terrace. From visual inspection in accessible location, no significant change observed.	Evidence of water ingress through the mortar joints, indicating perch groundwater behind wall could be present. No significant change in risk rating.	No significant change	Could not survey due to lack of access to mid-terrace. From visual inspection in accessible location, no significant change observed.	Could not survey due to no access to mid-terrace. From visual inspection in accessible location, no significant change observed.	Could not survey due to no access to mid-terrace. From visual inspection it appeared a small amount of water egress was occurring. Wall appeared wet in places. No significant change to risk profile.	Could not survey due to no access to mid-terrace. From visual inspection it appeared a small amount of water egress was occurring. Wall appeared wet in places. No significant change to risk profile.	Low	2	Unlikely	1	Very Low	2	Low
A14	Spa Beach Huts	403062	79353		Retaining wall height: 1.2m Retained height: 0m Vertical and horizontal cracking. Crack length 1.1m, crack width up to 10mm. No loose masonry or missing blockwork. No bulging or bowing of the wall structure.	Surveyed - No significant change.	No significant change	No significant change. Vegetation (flowers) observed to be growing through the cracks in the masonry.	Slight bulging of <10mm observed. Vegetation previously observed has died back. No significant change in risk profile.	Bulging approx. 10mm observed. No significant change	No significant change.	No significant change.	No significant change. Dislocation measured - approx 10mm still.	No significant change. Dislocation increased slightly - approx 10 - 20mm	Low	2	Unlikely	1	Very Low	2	Low
A15	Spa Beach Huts	403060	79377		Retaining wall height: 2.55m Retained height: 2.55m Vertical cracking, crack length 1.3m, typical crack width between 3 - 10mm. Bulging/bowing at corner section of masonry wall. Loss of mortar between blockwork.	Horizontal crack width 20mm max. Vertical crack width 20mm max. Otherwise no significant change.	No significant change	No significant change. Water egress / pooling at base of the wall, however origin of this was unconfirmed. No immediate signs of water expelling from the wall face.	Visual evidence of water egress from behind the wall in the upper sections. Lower sections of the wall are dry therefore assumed to not be due to rainfall. Pooling of water at the base of the wall believed to be due to dilapidated drainage at toe of wall.	October 2024 observation still valid re: water egress from behind the wall, and pooling of water at the base of the wall. Evidence of continued spalling of bottom layer of exposed masonry above concrete render at base. Recommend to continue monitoring for further signs of wall distress. No immediate preventative measures recommend as area is already isolated from the public.	Water egress still observed from the wall. Vegetation also noted growing from the wall in the cracks of the render. Vegetation is generally small. Could not comment on pooling water due to rainy weather although no significant pooling was noted. Max crack width of 20mm.	Water egress still observed from the wall. Vegetation is generally small. Pooling water not observed. Crack width unchanged (20mm)	No significant change since last inspection. Following are still valid (note ponding was observed in Feb 2026): Water egress still observed from the wall. Vegetation is generally small. Pooling water was observed. Crack width unchanged (20mm)	No significant change since last inspection. Previous observations relating to water were not observed. Crack width unchanged (20mm) Vegetation is generally small.	Medium	3	Likely	2	Low	6	Medium

Swanage Town Council - Shore Road - Asset Defect Schedule (February 2026)																February 2026 Risk Rating	August 2026 Risk Rating					
Defect Ref.	Defect Location	Easting (m)	Northing (m)	Sample Photo of Defect	Initial Defect Description (June 2023)	Defect Description (Oct 2023)	Defect Description (Feb 2024)	Defect Description (May 2024)	Defect Description (October 2024)	Defect Description (February 2025)	Defect Description (June 2025)	Defect Description (October 2025)	Defect Description (February 2026)	Defect Description (August 2026)	Risk Level	Likelihood (Number)	Likelihood	Effect (Number)	Effect	Risk Level (Number)	Risk Level	
A16	Spa Beach Huts	403060	79381		Retaining wall height: 2.55m Retained height: 2.55m Horizontal and vertical cracking. Crack length 1.6m. Typical crack width 3 - 10mm. Bulging/bowing at the mid span of masonry wall.	Surveyed - No significant change.	No significant change	No significant change	No significant change	No significant change	Crack length still 1.6m Horizontal shear still noted however the top portion has not moved to create an overhang as of yet.	No significant change	No significant change Crack width typically 10 - 30mm. Horizontal shear still noted however the top portion has not moved to create an overhang as of yet.	No significant change Crack width typically 10 - 30mm. Horizontal shear still noted however the top portion has not moved to create an overhang as of yet.	Low	1	Negligible	2	Low	2	Low	
A17	Spa Beach Huts	403062	79383		Retaining wall height: up to 2.2m Retained height: up to 2.5m. Horizontal cracking. Crack length 1.8m. Crack width 3 - 12mm. Horizontal movement of return wall causing cracking, potentially due to bulging/bowing from the main span.	Surveyed - No significant change.	No significant change	No significant change	No significant change	No significant change	maximum vertical crack width recorded to be 10mm. Horizontal crack width up to 5mm.	Vertical crack width 10 - 15mm. No significant change	Vertical crack width measured, still 10 - 15mm. No significant change	Vertical crack width slight increase 10 - 20mm. Horizontal cracks <5mm. Fall on steps approximately 2-3" No significant change	Low	1	Negligible	1	Very Low	1	Low	
A18	Spa Beach Huts	403026	79380		N/A	N/A	N/A	N/A	N/A	De Moulham Road Retaining Wall Observations: Approx. Defect Length = 18m - Overturning wall - Longitudinal tension cracking in pavement - Multiple tarmac repairs observed in the area. - Settlement of material adjacent to the retained side of the wall (underlying tarmac repair) - approx. 20-30mm. - Settlement consistent with theory of wall overturning, resulting in void developing behind wall for subbase/subgrade material to settle into. - Cracking in masonry wall consistent with location of cracks in the pavement, indicating cause/effect of wall on pavement construction. Likely cause of issue: - Poor foundation material, causing differential settlements - Leakage of drainage system in locale causing reduction in strength of the wall formation material.	The pavement has been resurfaced since the last inspection. No cracks present on new surfacing. Area below masonry wall fenced off from the public. Wall has minor cracking and vegetation growing in the mortar render between the blocks. Desiccation noted in the toe area.	Desiccation not observed at the toe. New surfacing is showing minor cracking, and on either end of the repair cracks are extending parallel to the wall. Subsidence of the pavement is also present.	Minor leaning of the wall below measured to be 2" - 3". Desiccation not observed at toe, likely due to wet weather. New patch repair has been completed since October 2025 visit. New surfacing is showing minor cracking, and on either end of the repair cracks are extending parallel to the wall. No significant change since February 2025 survey Subsidence of the pavement is also present.	Could not observed wall condition from below due to vegetation cover. Dessication not observed. Previous repairs noted. New surfacing is showing minor cracking, and on either end of the repair cracks are extending parallel to the wall. No significant change since February 2025 survey Subsidence of the pavement is also present.	Medium	3	Likely	2	Low	6	Medium	
A19	Spa Beach Huts	403063	79367		N/A	N/A	N/A	N/A	N/A	N/A	N/A	Cracking in wall at base of steps. Retaining wall 2.5m in height. Crack approx. 1m long and width of up to 30mm.	Minor seepage observed. Crack width 30 - 40mm.	Minor seepage observed. Crack width 30 - 45mm. No significant change to risk profile.	Crack width 30 - 50mm. No significant change to risk profile.	Low	1	Negligible	2	Low	2	Low
A20	Spa Beach Huts	403059	79368		N/A	N/A	N/A	N/A	N/A	N/A	N/A	Cracking noted on the south end of the wall with defect A16. Cracking observed within render between blocks. Crack length 1m Crack width up to 20mm.	No significant change.	No significant change.	No significant change.	Low	1	Negligible	2	Low	2	Low

Swanage Town Council - Shore Road - Asset Defect Schedule (February 2026)																February 2026 Risk Rating	August 2026 Risk Rating					
Defect Ref.	Defect Location	Easting (m)	Northing (m)	Sample Photo of Defect	Initial Defect Description (June 2023)	Defect Description (Oct 2023)	Defect Description (Feb 2024)	Defect Description (May 2024)	Defect Description (October 2024)	Defect Description (February 2025)	Defect Description (June 2025)	Defect Description (October 2025)	Defect Description (February 2026)	Defect Description (August 2026)	Risk Level	Likelihood (Number)	Likelihood	Effect (Number)	Effect	Risk Level (Number)	Risk Level	
A21	Spa Beach Huts	403027	79364			N/A	N/A	N/A	N/A	N/A	Buttresses on retaining wall adjacent to defect A9 are delaminating from retaining wall. Render is cracked between buttress and wall. Crack width of 30mm. Retaining wall 1.3m height and 1.0m depth.	No significant change.	Seepage observed on abutment and the wall it is supporting. Crack widths measured to be 30 - 40mm.	No significant change Seepage not observed	Medium	2	Unlikely	3	High	6	Medium	
A22	Spa Beach Huts	403064	79377			N/A	N/A	N/A	N/A	N/A	N/A	Seepage observed in lower wall below beach huts. Several areas were noted on a dry day.	Seepage observed in lower wall below beach huts. Inspection after a period of wet weather, significant signs of water egress noted all over.	Seepage not observed.	Low	2	Unlikely	2	Low	4	Low	
A23	Spa Beach Huts	403058	79387			N/A	N/A	N/A	N/A	N/A	N/A	Vertical cracking observed in wall. Widths <10mm. Cracking in place of mortar between blocks. Retaining wall height = 0.9m. Retaining wall depth = 0.4m.	No significant change. Cracking measured to be <10mm. A small pavement crack, running across the footpath was observed at the toe. Spoil on top of the wall still present, does not appear to have changed in quantity since October 2025.	No significant change. Cracking measured to be 10-15mm. A small pavement crack, running across the footpath was still noted, it doesn't appear to have changed in condition since last survey. Spoil on top of the wall still present, does not appear to have changed in quantity since October 2025.	Low	2	Unlikely	1	Very Low	2	Low	
A24	Spa Beach Huts	403051	79385			N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Vertical cracking in the wall observed. Retained height 1m, width 0.3m. Crack length 1m. Crack Width <60mm (largest at the toe) Cracking observed on the corner wall adjacent to the steps. Lower blocks have no mortar between them. Low height retaining wall which is reflected in the low risk profile.	Low	1	Negligible	2	Low	2	Low	
B1	Weather Station Field	403050	79339		Pavement tension cracking, surface deformation and partial collapse. 2no. continuous cracks observed, 3.6m and 11m in length respectively. Multiple patch repairs with asphalt and cement/concrete mix. Ground uneven and with numerous cracks. Crack depths ranging between 5 - 10mm where repairs have not been completed.	Surveyed - No significant change. Slip/trip/fall hazard for members of the public (similar to defect ref. C7). Consider closing off access to footpath, or removing entirely.	Footpath now removed and replaced with grass	No significant change.	No significant change.	No significant change Repair still intact.	No significant change. Bare earth noted on old path location, grass growing in patches.	No significant change. More grass cover over bare earth. Occasional bare earth.	No significant change. More grass cover over bare earth. Occasional bare earth.	No significant change. More grass cover over bare earth. Occasional bare earth.	Low	1	Negligible	1	Very Low	1	Low	

Swanage Town Council - Shore Road - Asset Defect Schedule (February 2026)															February 2026 Risk Rating	August 2026 Risk Rating								
Defect Ref.	Defect Location	Easting (m)	Northing (m)	Sample Photo of Defect	Initial Defect Description (June 2023)	Defect Description (Oct 2023)	Defect Description (Feb 2024)	Defect Description (May 2024)	Defect Description (October 2024)	Defect Description (February 2025)	Defect Description (June 2025)	Defect Description (October 2025)	Defect Description (February 2026)	Defect Description (August 2026)	Risk Level	Likelihood (Number)	Likelihood	Effect (Number)	Effect	Risk Level (Number)	Risk Level			
B2	Weather Station Field	403042	79330		In the field area to the east of weather station, hummocky ground observed, with tension cracking in slope, bulging of surface.	Surveyed - No significant change.	No significant change	No significant change	At south east corner of field, a BH / inclinometer cap missing, with open pipework exposed. This is likely to cause erroneous recordings with regards to groundwater measurements. Review of data to be undertaken. Bulging of surface slope material remains, and hummocky ground building up behind wall running to the south.	BH cap at south east corner has been replaced since last inspection. Rectified. Bulging slope surface shows no significant change. However, still presents a remedial risk. Regular topographical survey works would be required to assess minor slope movements. Risk of failure to the south reduced with the erection of an exclusion zone around southern wall section.	Hummocky ground with desiccated ground in areas. Bulging slope surface shows no significant change. However, still presents a remedial risk. Regular topographical survey works would be required to assess minor slope movements.	No significant change Regular topographical survey works would be required to assess minor slope movements.	No significant change Area was significantly wet under foot. Soft ground around the weather station and above in line with saturation. Regular topographical survey works would be required to assess minor slope movements.	No significant change Area no longer wet underfoot. Regular topographical survey works would be required to assess minor slope movements.	Medium	3	Likely	2	Low	6	Medium			
B3	Weather Station Field	403059	79309		Retaining wall height: 1.8m Retained height: 1.8m Vertical and horizontal cracking, crack width between 2 - 20mm, occurring at apex of wall curvature. No bulging or bowing of the wall observed.	Unable to survey position of maximum crack width due to information signage location. Otherwise no significant change observed.	No significant change	No significant change	No significant change	No significant change	Crack width adjacent to warning sign surveyed. Max opening of 35mm. No significant change in condition.	No significant change.	Crack width adjacent to warning sign surveyed. Max opening of 35mm. No significant change.	Crack width adjacent to warning sign surveyed. Max opening of 35mm. No significant change.	Low	2	Unlikely	2	Low	4	Low			
B4	Weather Station Field	403055	79305		Retaining wall height: 1.8m Retained height: 1.8m Curved wall with 3no. sets of vertical cracking. From south face of retaining wall, cracks are at chainage CH 0, 2.0, and 5.5m. Total length of defect: 5.5m. CH 0m Defect: Vertical cracking, crack width typically 30 - 50mm. Missing blockwork at the head of the wall, with significant voids behind mid span of wall (potentially lost mortar or block work following movement). CH 2.0m Defect: Vertical cracking, max crack width typically 90 - 130mm, increasing with height of wall. Missing blockwork at top of wall. CH 5.5m Defect: Vertical cracking, crack width up to 10mm. Blockwork intact.	Survey of crack dimensions hampered by heras fencing panels, which could not be moved. Could not be surveyed accurately. No significant change in structure compared with previous survey. Maintain heras fencing panel around defect. Continue to monitor regularly.	Heras fencing forming exclusion zone. No direct measurements made, however general observations indicate further movement. Continue to monitor and maintain exclusion.	Heras fencing forming exclusion zone. No direct measurements made, due to presence of fencing panels. Continue to monitor and maintain exclusion.	No significant change. Continue to monitor and maintain exclusion zone.	No significant change. Continue to monitor and maintain exclusion zone.	No significant change. Continue to monitor and maintain exclusion zone.	No significant change. Continue to monitor and maintain exclusion zone.	No significant change. Continue to monitor and maintain exclusion zone.	No significant change. Cacking measured <70mm Continue to monitor and maintain exclusion zone.	No significant change. Cacking measured <70mm Continue to monitor and maintain exclusion zone.	No significant change. Cacking measured <70mm Continue to monitor and maintain exclusion zone.	No significant change. Cacking measured <70mm Continue to monitor and maintain exclusion zone.	High	3	Likely	3	High	9	High
B5	Weather Station Field	403054	79310		Vertical cracking on footpath/stepped access. Crack length 3m, typical crack width 1-2mm.	Additional cracking observed at bottom left stairs area. Crack widths similar to previous survey.	No significant change	Additional loss of material/concrete from steps, with voids/cracking up to 40-50mm observed. No significant change to risk level currently.	Additional cracking of pavement slabs observed. No significant change to risk profile.	Significant cracking of pavement slabs. Concrete pavers still stable (i.e. no rocking), however continued deterioration of the asset may give cause to a trip hazard. Recommend to continue monitoring. No significant change in geotechnical risk profile.	Concrete pavement slabs still stable (i.e. no rocking), however continued deterioration of the asset may give cause to a trip hazard. Recommend to continue monitoring. No significant change in geotechnical risk profile.	Concrete pavement slabs still stable (i.e. no rocking), however continued deterioration of the asset may give cause to a trip hazard. Recommend to continue monitoring. No significant change in geotechnical risk profile.	Concrete pavement slabs still stable (i.e. no rocking), however continued deterioration of the asset may give cause to a trip hazard. Recommend to continue monitoring. No significant change in geotechnical risk profile.	Concrete pavement slabs still stable (i.e. no rocking), however continued deterioration of the asset may give cause to a trip hazard. Recommend to continue monitoring. No significant change in geotechnical risk profile.	Low	2	Unlikely	1	Very Low	2	Low			

Swanage Town Council - Shore Road - Asset Defect Schedule (February 2026)															February 2026 Risk Rating	August 2026 Risk Rating					
Defect Ref.	Defect Location	Easting (m)	Northing (m)	Sample Photo of Defect	Initial Defect Description (June 2023)	Defect Description (Oct 2023)	Defect Description (Feb 2024)	Defect Description (May 2024)	Defect Description (October 2024)	Defect Description (February 2025)	Defect Description (June 2025)	Defect Description (October 2025)	Defect Description (February 2026)	Defect Description (August 2026)	Risk Level	Likelihood (Number)	Likelihood	Effect (Number)	Effect	Risk Level (Number)	Risk Level
B6	Weather Station Field	403045	79304		Retaining wall height: 1.0m. Retained height: 1.5m. Vertical and horizontal cracking, crack length 0.8m. Typical crack width 40 - 60mm. Minor bowing of the wall at mid height.	Previously identified "minor bowing" appears more akin to shearing of top row of finishing stones of wall span, from the wall below. No significant change in crack widths from previous survey.	No significant change in crack widths Noted to be very wet with water issuing from between cracks	No significant change. No water observed expelling from the wall face, however weather conditions were dry on date of inspection.	Top of wall has sheared further outwards from lower wall. No significant change in risk profile.	Max crack width increased from 60mm to 90mm. Top of wall has sheared further outwards from lower wall. Significant water egress from wall face at joint with flag stones. Increased geotechnical risk, however risk profile has been kept same, due to limited exposure risk following installation of exclusion zone at Walrond Road north.	Max crack width 90mm. Overhang from top section (shear failure) up to 45mm. No significant change.	No significant change. Crack widths and overhang not increased.	No significant change. Crack widths and overhang not increased. Seepage was observed through the cracks.	No significant change. Crack widths and overhang not increased. Seepage not observed	Low	2	Unlikely	1	Very Low	2	Low
B7	Weather Station Field	403034	79304		Retaining wall height: 0.9m Retained height: 1.0m. Vertical cracking, from base to top of wall (i.e. 0.9m), crack width between 20 - 40mm.	Surveyed - No significant change.	No significant change	No significant change	No significant change	Significant water egress from wall face at joint with flag stones. Increased geotechnical risk, however risk profile has been kept same, due to limited exposure risk following installation of exclusion zone at Walrond Road north.	Vertical crack width measured to be between 20 - 50mm. No water egress noted however this may have been masked by the heavy rainfall present during the monitoring visit.	No significant change. Crack widths still similar. Water egress noted in February 2025 not observed on dry day either.	No significant change. Vertical crack width measured to be between 20 - 50mm. Seepage observed from cracks.	No significant change. Vertical crack width measured to be between 20 - 50mm. Seepage not observed from cracks.	Low	1	Negligible	1	Very Low	1	Low
B8	Weather Station Field	403026	79304		Retaining wall height: 0.85m Retained height: 1m + Vertical and horizontal cracking, the full height of the wall (0.85m), with typical crack width of 20mm. Lower right side (east) of wall translational movement relative to rest of wall (<30mm).	Max crack width increased to up to 40mm. Otherwise no significant change - low risk.	No significant change	No significant change	No significant change	No significant change	Crack widths measured between 20 - 30mm. No significant change.	No significant change. No increase in crack width measured.	No significant change. Crack widths measured between 20 - 30mm. Overhang / translational movement up to 30mm.	No significant change. Crack widths measured between 20 - 30mm. Overhang / translational movement up to 30mm.	Low	1	Negligible	1	Very Low	1	Low
B9	Weather Station Field	403017	79304		Retaining wall height: 1.0m Retained height: 1.0m Vertical cracking, running full height of the wall. Right of the crack (east side of the wall), 30mm translational movement of the wall relative to the west side. Pavement cracking adjacent to retaining wall observed from base of retaining wall.	Surveyed - No significant change.	No significant change	Crack width observed up to 20mm. No significant change to translation movement or pavement cracking adjacent to the wall.	No significant change	No significant change	Crack width measured up to 20mm. No significant change.	No significant change. No increase in crack width measured.	No significant change. Vertical crack widths 10 - 20mm. Translational movement <30mm.	No significant change. Vertical crack widths 10 - 20mm. Translational movement <30mm.	Low	1	Negligible	1	Very Low	1	Low

Swanage Town Council - Shore Road - Asset Defect Schedule (February 2026)																				February 2026 Risk Rating	August 2026 Risk Rating					
Defect Ref.	Defect Location	Easting (m)	Northing (m)	Sample Photo of Defect	Initial Defect Description (June 2023)	Defect Description (Oct 2023)	Defect Description (Feb 2024)	Defect Description (May 2024)	Defect Description (October 2024)	Defect Description (February 2025)	Defect Description (June 2025)	Defect Description (October 2025)	Defect Description (February 2026)	Defect Description (August 2026)	Risk Level	Likelihood (Number)	Likelihood	Effect (Number)	Effect	Risk Level (Number)	Risk Level					
B10	Weather Station Field	403040	79304			N/A Retaining wall height: 0.9m Retained height: 1.0m. Vertical cracking, from base to top of wall (i.e. 0.9m), crack width up to 10mm.	No significant change	No significant change	No significant change	No significant change Significant overhang of upper flag stone sections to lower wall. Risk covered under defect Ref. B11.	Pavement rutting noted at toe of wall. No significant change in the condition of the wall.	No significant change.	No significant change. Crack widths <10mm.	No significant change. Crack widths <10mm.	Low	2	Unlikely	1	Very Low	2	Low					
B11	Weather Station Field	403040	79304			N/A 7.5m length of wall, between defect ref. B6 and B7: Shearing of top span of masonry from base of wall, up to 50mm. Movement in superficial material on retained side of weather station field separating wall at weak/mortar joint location. Risk of collapse over time, and damage to pavement, members of the public, and cars parked on road adjacent to wall. Advise to continue monitoring regularly.	Shearing of top span of masonry from base of wall, increased to 70mm. Evidence of seepage through wall, along extents.	Condition of asset as per February 2024 inspection. Lateral extents of the defect has increased from 7.5m to 9m. Advise to continue monitoring - should further degradation to asset condition be observed, a footpath diversion may be required.	Length of defect observed increased from 7.5m to 10m. Significant evidence of seepage egressing from behind the wall, between the upper and lower wall sections. Evidence of spalling of facing material in multiple locations. Continue to monitor, if further degradation occurs, or additional spalling of wall material, consider exclusion zone around affected section and footpath diversion.	Exclusion zone has been erected since previous site walkover over (October 2024), in accordance with report recommendations. Longitudinal cracking + footpath bulge/heaving at locations of worst affected area + max slumping of material above wall. Recommend to maintain exclusion zone and regularly monitoring in accordance with main report recommendations.	Depression noted in the pavement at the toe of the wall. No significant change in wall condition. Recommend to maintain exclusion zone and regularly monitoring in accordance with main report recommendations.	No significant change. All June 2025 observations still apply. Recommend to maintain exclusion zone and regularly monitoring in accordance with main report recommendations.	No significant change. All June 2025 observations still apply. Recommend to maintain exclusion zone and regularly monitoring in accordance with main report recommendations. Shear movement <70mm. Seepage observed from cracking. Rutting at the toe of the wall observed.	No significant change. All June 2025 observations still apply. Recommend to maintain exclusion zone and regularly monitoring in accordance with main report recommendations. Shear movement <70mm. Rutting at the toe of the wall observed. Seepage not observed from cracking.	High	3	Likely	3	High	9	High					
C1	Sandpit Field	403000	79294		Retaining wall height: 1.0m. Retained height: 1.0m. Vertical cracking, full height of wall, typical crack width 5 - 30mm. Large bushes overhanging back of retaining wall, likely the cause of distress observed in the structure.	Displacement of east side of wall relative to the west up to 30mm. Otherwise no significant change - low risk.	No significant change	No significant change	Typical crack width increased from 30mm to 40mm. No significant change in asset risk.	No significant change	No significant change	No significant change in wall condition. Wall lower down the slope measured to be 20 - 30mm in front of the upper wall. Continue to monitor.	No significant change in wall condition. Wall lower down the slope measured to be 20 - 30mm in front of the upper wall. Continue to monitor.	No significant change in wall condition. Wall lower down the slope measured to be 20 - 30mm in front of the upper wall. Continue to monitor. Vertical cracking 5-30mm.	Low	2	Unlikely	1	Very Low	2	Low					
C2	Sandpit Field	403009	79294		Retaining wall height: 0.8m Retained height: 0.8m Vertical cracking full height of wall, typical crack width 5 - 20mm. Evidence of historic patch repair made previously.	Surveyed - No significant change.	No significant change	No significant change	No significant change	No significant change	No significant change	No significant change	No significant change	No significant change	Low	1	Negligible	1	Very Low	1	Low					

Swanage Town Council - Shore Road - Asset Defect Schedule (February 2026)																February 2026 Risk Rating	August 2026 Risk Rating					
Defect Ref.	Defect Location	Easting (m)	Northing (m)	Sample Photo of Defect	Initial Defect Description (June 2023)	Defect Description (Oct 2023)	Defect Description (Feb 2024)	Defect Description (May 2024)	Defect Description (October 2024)	Defect Description (February 2025)	Defect Description (June 2025)	Defect Description (October 2025)	Defect Description (February 2026)	Defect Description (August 2026)	Risk Level	Likelihood (Number)	Likelihood	Effect (Number)	Effect	Risk Level (Number)	Risk Level	
C3	Sandpit Field	403024	79295		Retaining wall height: 0.95m Retained height 1.0m Vertical cracking, full height of wall, crack width between 1 - 3mm.	Surveyed - No significant change.	No significant change	No significant change	No significant change	No significant change	No significant change	No significant change	No significant change. Seepage from the wall observed	No significant change. Seepage not observed	Low	1	Negligible	1	Very Low	1	Low	
C4	Sandpit Field	403035	79295		Retaining wall height: 1.0m Retained height: 1.2m Vertical cracking, full height of wall. Crack width 20 - 40mm.	Small void at base of wall due to loss of mortar/masonry. Likely lost from translational movement of the wall. Otherwise no significant change.	No significant change	No significant change	Masonry appears to have been lost / fallen off of wall face in section surrounding the crack (see latest images for comparison). Slight increase in asset risk, however still low due to general condition and retained height.	No significant change	No significant change	No significant change Crack widths still 20 - 40mm.	No significant change Crack widths still 20 - 40mm.	No significant change Crack widths still 20 - 40mm.	Low	2	Unlikely	2	Low	4	Low	
C5	Sandpit Field	403058	79290		Retaining wall height: 1.25m Retained height: 1.25m Vertical and horizontal cracking, typical crack width 20 - 30mm. Transverse movement of the wall, mortar joint failure from masonry blockwork moving apart.	Vertical and horizontal cracking increased from 20-30mm to 40-50mm. Otherwise health of asset unchanged. Low risk.	No significant change	No significant change	No significant change	No significant change	No significant change	Increase in crack widths measured, latest measurements between 40 - 60mm. Wall appears in good condition despite crack increase.	Crack widths measured to be 40 - 60mm. No significant change in wall condition or risk profile.	Crack widths still measured at approximately 40 - 60mm. No significant change in wall condition or risk profile.	Low	2	Unlikely	2	Low	4	Low	
C6	Sandpit Field	403054	79280		Retaining wall height: 0.6m Retained height: 1.5m+ Vertical cracking full height of the wall. Typical crack width between 10 - 15mm. Overgrown bushes and vegetation acting on the back of the wall the likely cause of deterioration of the retaining structure.	Typical crack width increased to 15-25mm. Otherwise no significant change - low risk.	No significant change	No significant change	No significant change. Asset partially obscured by vegetation.	No significant change. Asset partially obscured by vegetation.	Vegetation cover obscuring asset. Flagstone from wall noted to have fallen onto step above defect. See report for photos. Block approximately 0.4 x 0.4 x 0.1m in size. No significant change to crack.	Vegetation cover obscuring asset. No significant change to crack. Block noted in the June 2025 inspections has been moved up the steps.	Vegetation cover obscuring asset. No significant change to crack, measured to b 15 - 25mm. Ponding was observed at the toe of the wall, the wall itself was wet indicating water egress. Block noted in the June 2025 inspections has been moved.	Vegetation cover obscuring asset. No significant change to crack, measured to b 15 - 25mm. Block noted in the June 2025 inspections has been moved. The ponding observed previously was not present during this walkover.	Low	2	Unlikely	2	Low	4	Low	

Swanage Town Council - Shore Road - Asset Defect Schedule (February 2026)															February 2026 Risk Rating	August 2026 Risk Rating					
Defect Ref.	Defect Location	Easting (m)	Northing (m)	Sample Photo of Defect	Initial Defect Description (June 2023)	Defect Description (Oct 2023)	Defect Description (Feb 2024)	Defect Description (May 2024)	Defect Description (October 2024)	Defect Description (February 2025)	Defect Description (June 2025)	Defect Description (October 2025)	Defect Description (February 2026)	Defect Description (August 2026)	Risk Level	Likelihood (Number)	Likelihood	Effect (Number)	Effect	Risk Level (Number)	Risk Level
C7	Sandpit Field	403057	79248		Multiple areas of pavement cracking and surface deformation (one example shown face left). Distress in asphalt behind lower slope retaining walls observed where rotation of lower wall was seen (see defect C13). Additional areas of distress in pavement seen where up slope area is over steepened and not effectively restrained by retaining structure or otherwise, see defect C12.	Defect has been repaired, asphalt has been re-laid in area following slip/trip/fall incident. Bench removed from area. Area to be checked in follow up surveys to ensure defect does not reoccur.	No significant change	No significant change	No significant change Current pavement repair has held.	No significant change. Pavement repair in good condition.	Pavement repair in good condition. Minor cracking in the surface of the unrepaired section of pavement. Cracks approximately 5mm. Debond noted between pavement repair and unrepaired section.	No significant change - June 2025 observations all still apply.	No significant change - June 2025 observations all still apply.	No significant change - June 2025 observations all still apply.	Low	1	Negligible	1	Very Low	1	Low
C8	Sandpit Field	403056	79252		Retaining wall height: 1.3m Retained height 3.0m + 61.m of terraced masonry blocks which were observed to be overturning with over steepened slope behind. Blocks likely installed to prevent shallow slip failure of material above, however global stability of slope borderline.	Blocks further overturned. Further ravelling of slope material. A 1 m section of toe has a paving stone/blockwork missing. Unsupported toe area has an increased risk of slip/localised slope failure. Regular inspection of area recommended to inspect condition. Consider replacing stone/blockwork to provide support to the face.	No significant change	2no. Replacement blockwork paving slabs installed on the base row. Southern one has already overturned with voiding behind the rear face of panel observed. Advise to continue monitoring these slabs. If these significantly overturn or come loose they could present a trip hazard to pedestrians.	Southern paving slab referred to within May 2024 defect schedule has been repaired/reinstated. Continue to monitor, however risk profile remains same from May 2024 inspection.	No significant change. Asset partially obscured by vegetation.	Vegetation cover obscuring asset. No significant change.	Vegetation cover obscuring asset. No significant change.	Vegetation cover obscuring asset. No significant change.	No significant change. Hummocky ground and tension cracks observed on the slope face. Small channel observed on the slope, reportedly due to people climbing / sliding down the slope. Approx 180-240mm width,	Medium	2	Unlikely	3	High	6	Medium
C9	Sandpit Field	403056	79246		Retaining wall height: 0.6m Retained height: 3m + 7.51m of retaining wall blocks partially overturned at toe of retaining wall. Insufficient embedment of blocks at toe, and over steepened slope behind overloading wall.	Surveyed - No significant change.	Slabs appear to have rotated further outward, consider removal or replacement	Further overturning of southern most slab and newly replaced slab observed. Consider removal and reinstatement with greater toe embedment.	Southern most slab has been repaired/replaced and levelled. Continue to monitor.	No significant change. Continue to monitor pavers for movement/displacement.	No significant change. Continue to monitor pavers for movement/displacement.	No significant change. Continue to monitor pavers for movement/displacement. Distortion measured to be up to 11"	No significant change. Continue to monitor pavers for movement/displacement. Distortion measured to be up to 12"	No significant change. Continue to monitor pavers for movement/displacement. Distortion measured to be up to 12"	Low	2	Unlikely	2	Low	4	Low
C10	Sandpit Field	403052	79239		31.m of tension cracking observed in oversteep section of slope. Width of tension crack approx. 200mm, and 250mm depth in areas.	Tension crack width Otherwise no significant change. Continue to monitor on ongoing basis.	No significant change	No significant change.	No significant change. Due to heavy vegetation, quantifying the crack width of asset difficult. From general visual inspection, asset condition has not changed since previous inspection.	Area de-vegetated following previous inspection circa October 2024. Hummocky ground and tension crack on embankment toe observed, resulting in 200-300mm vertical face of material. Recommend to continue monitoring for further degradation.	Hummocky ground covered in vegetation so tension crack could not be measured. Slight subsidence noted in the pavement above the slope however the condition is generally okay. No significant change to geotechnical risk profile.	Hummocky ground covered in vegetation so tension crack could not be measured. No significant change to geotechnical risk profile.	Hummocky ground covered in vegetation so tension crack could not be measured. No significant change to geotechnical risk profile.	Hummocky ground covered in vegetation so tension crack could not be measured. No significant change to geotechnical risk profile.	Medium	3	Likely	2	Low	6	Medium

Swanage Town Council - Shore Road - Asset Defect Schedule (February 2026)															February 2026 Risk Rating	August 2026 Risk Rating					
Defect Ref.	Defect Location	Easting (m)	Northing (m)	Sample Photo of Defect	Initial Defect Description (June 2023)	Defect Description (Oct 2023)	Defect Description (Feb 2024)	Defect Description (May 2024)	Defect Description (October 2024)	Defect Description (February 2025)	Defect Description (June 2025)	Defect Description (October 2025)	Defect Description (February 2026)	Defect Description (August 2026)	Risk Level	Likelihood (Number)	Likelihood	Effect (Number)	Effect	Risk Level (Number)	Risk Level
C11	Sandpit Field	403055	79235		Retaining wall height: 0.3m Retained height: 3m+ 2.1m section of retaining wall at the rear of benches, has overturned by 30 degrees from vertical. Large overgrown vegetation acting immediately behind the rear of wall, likely cause of issue.	Overturning of retaining wall increased to 45 degrees from vertical. Low risk, however continue to monitor. Risk of causing hazards related to slips/trip/falls, particularly adjacent to bench + pedestrian walkway.	Evidence of increased tilt - continue to monitor.	Evidence of increased tilt compared to Feb 2024	No significant change	Significant overturning of paving slabs observed, almost to the horizontal. Small risk of material and flagstone movement into the footway, causing slip / trip / fall hazard. Recommend overturned slabs are removed, area made good and slabs reinstated. Continue to monitor for further degradation between site walkover surveys.	Pavement slabs still overturning, no significant change in angle. Slabs behind the bench also overturning. Recommend overturned slabs are removed, area made good and slabs reinstated. Continue to monitor for further degradation between site walkover surveys.	Pavement slabs still overturning, no significant change in angle. Recommend overturned slabs are removed, area made good and slabs reinstated. Continue to monitor for further degradation between site walkover surveys.	Pavement slabs still overturning, no significant change in angle. Recommend overturned slabs are removed, area made good and slabs reinstated. Continue to monitor for further degradation between site walkover surveys. Pavement cracking was observed on the footpath below the bench, cracking was shallow and noted in the surface over a length of approximately 8m.	Pavement slabs still overturning, no significant change in angle. Measured at 22° Recommend overturned slabs are removed, area made good and slabs reinstated. Continue to monitor for further degradation between site walkover surveys. Pavement cracking still observed on the footpath below the bench, cracking was shallow and noted in the surface over a length of approximately 8m. Several cracks observed.	Medium	3	Likely	2	Low	6	Medium
C12	Sandpit Field	403055	79202		3no. Failed retaining wall which use to house benches. Retaining wall height: 0.6m Retained height 2.5 - 3.5m + Masonry wall fully overturned and collapse of the main wall span. Partial collapse of the return walls either side of each retaining wall. Bulging and hummocking of stone slab at ground level, and signs of distress in adjacent asphalt where retaining walls have failed, indicating greater/deeper global failure occurring.	2nd/Middle retaining wall: - increased raveling of shallow material observed. - Shallow slip developing above overturned masonry. Considering heras fencing, cordoning off. Retaining Walls 1 + 3: Surveyed - No significant change observed.	Infilled with sleepers and planting - tension cracking noted above this section and above adjacent retaining walls. Continue to monitor. It is advised that the remaining bench is removed in this section.	Remaining bench has been removed. In addition to Feb 2024 observations, footway adjacent to the bench area has been re-paved. Tension cracking in the slope above the bench areas still observed - advise to continue monitoring.	No significant change from May 2024 inspection. Continue to monitor top slope, as there is still significant signs of slope distress.	No significant change from October 2024 inspection. Continue to monitor top slope, as there is still significant signs of slope distress.	Slight overtopping of concrete end slabs between walls 1 & 2. No significant change in wall conditions.	No significant change in wall conditions. Sleepers starting to undergo weathering and slight rotting. Continue to monitor.	No significant change in wall conditions. Sleepers starting to undergo weathering and slight rotting. Continue to monitor. 3rd wall showing a slight overturning of approximately 3° - Continue to monitor.	Medium	3	Likely	2	Low	6	Medium	
C13	Sandpit Field	403057	79207		Retaining wall height: 1.0m Retained height: 0.3m Minor tilt/overturning observed in section of masonry wall. Area of overturning matches asphalt repairs and scarring work indicating link between the two. Defect length 22.1m.	Surveyed - No significant change.	No significant change. Footway resurfaced.	No significant change.	No significant change.	No significant change.	Small longitudinal crack in top step of masonry wall. Crack width 10mm wide and 1.1m long. Pavement surfacing still in good condition.	No change in crack dimensions. Pavement surfacing still in good condition. A few of the top stones noted to be loose, these may fall if knocked by members of the public sitting on the wall. Minimal risk due to size however may need mortaring back in place	Crack still measured <10mm width and 1.1m long. Pavement surfacing still in good condition. A few of the top stones noted to be loose, these may fall if knocked by members of the public sitting on the wall. Minimal risk due to size however may need mortaring back in place	Crack on top of wall repointed. Loose blocks repaired. A small crack, approximately 250mm long and 3-4mm wide remains. Pavement surface in okay condition, minor cracks 4.5m long and approx 3-5mm wide.	Low	2	Unlikely	2	Low	4	Low
C14	Sandpit Field	403039	79146		Retaining wall height: 1.25m Retained height: 1.25m Lack of mortar joints connecting this section of wall, therefore potential reconstruction of wall section with dry stone wall technique. Mid height bulging/bowing of the wall likely due to large bushes/trees directly overhanging the back of the wall. Defect length approx. 6.1m.	Significant bow in the wall, due to large bushes/trees directly overhanging back of the wall. Bow/overturn measured as 7 degrees to the vertical. Recommended that trees are coppiced, to remove load from back of the wall, and limit damage to wall without killing tree. Killing or removing the tree would cause the decay/rotting of root system, which is likely providing some integrity to the wall structure.	No significant change.	No change to the condition of the wall. Reduction in risk rating considered due to removal of tree/load from rear face of wall.	No significant change.	No significant change.	No significant change.	No significant change. Still minimal mortar between blocks. Slight overtopping at base observed.	No significant change. Still minimal mortar between blocks. Slight overtopping at base observed.	No significant change. Still minimal mortar between blocks. Slight overtopping at base observed.	Low	1	Negligible	2	Low	2	Low

Swanage Town Council - Shore Road - Asset Defect Schedule (February 2026)																February 2026 Risk Rating	August 2026 Risk Rating					
Defect Ref.	Defect Location	Easting (m)	Northing (m)	Sample Photo of Defect	Initial Defect Description (June 2023)	Defect Description (Oct 2023)	Defect Description (Feb 2024)	Defect Description (May 2024)	Defect Description (October 2024)	Defect Description (February 2025)	Defect Description (June 2025)	Defect Description (October 2025)	Defect Description (February 2026)	Defect Description (August 2026)	Risk Level	Likelihood (Number)	Likelihood	Effect (Number)	Effect	Risk Level (Number)	Risk Level	
C15	Sandpit Field	403041	79295		N/A	N/A	N/A	Retaining wall height: 0.9m Retained height 0.9m Vertical cracking, full height of wall, hairline cracking of width up to 2mm.	No significant change	No significant change	No significant change	Vertical crack width measured up to 70mm. No significant change in risk profile.	Vertical crack width measured up to 70mm. Seepage observed in the crack and from the render below the flagstones. No significant change in risk profile.	Vertical crack width measured up to 70mm. No seepage observed. No significant change in risk profile.	Low	1	Negligible	1	Very Low	1	Low	
C16	Sandpit Field	403053	79295		N/A	N/A	N/A	Retaining wall height: 1.0m Retained height 1.0m Vertical cracking, full height of wall, cracking up to 50mm.	No significant change	No significant change	No significant change	No significant change	No significant change Crack widths <50mm. Seepage observed from the crack.	No significant change Crack widths <50mm. Seepage not observed.	Low	1	Negligible	1	Very Low	1	Low	
C17	Sandpit Field	403503	9208		N/A	N/A	N/A	N/A	N/A	N/A	N/A	2 new retaining walls installed on the footpath further north of C12. Sleeper retaining wall 1 (Furthest north) Height 0.5m, depth 0.25m, length 2.35m. 4 wooden railway sleepers bolted to the floor and each other in front of stone retaining wall which the client reported as having slipped. Backfilled with soil behind wooden wall.	No significant change in new retaining walls.	No significant change in new retaining walls.	No significant change in new retaining walls.	Medium	3	Likely	2	Low	6	Medium
C18	Sandpit Field - Gun turret	403046	79255		N/A	N/A	N/A	N/A	N/A	N/A	N/A	New defect reported by the client on gun turret in sandpit field. Reported as follows - Collapse of buried wall (believed to be supporting tunnel) underground causing a hole to open up and minor subsidence. The hole has been boarded up and the contractor is to return to site and pack stone under the corner of the slab that is now unsupported due to collapsed wall. Desiccation noted on the earth mound above the tunnels.	No significant change. Desiccation previously observed is forming small tension cracks in the bank. Tension cracking observed between fill and structure, minimal risk to public safety due to low height earthwork.	No significant change in structure condition / boarding. Tension cracking and minor desiccation still observed however due to wet weather and saturation of the material these appear to be smaller. The field around the gun turret is heavily saturated underfoot.	The Client had observed subsidence on the steps above the tunnels and hence removed the boarding on the side for this visit. On inspection the front wall below the tunnel had collapsed further, and is now leaning on the back wall. The back wall is also leaning into the tunnel, hence minimal support from the walls is being provided to the slab above. Subsidence was observed on the north side of the steps above, and the grass area between the two concrete slabs also showed subsidence. Tension cracking and desiccation was observed on the mound around the ammo room to the rear of the emplacement. The field area was dry underfoot compared to the saturated ground previously observed.	Medium	4	Probable	3	High	12	High
C19	Sandpit Field	403507	79280		N/A	N/A	N/A	N/A	N/A	N/A	N/A	Crack on the road face of the retaining wall around the steps. Crack on the corner of the south wall. Retaining wall dimensions - Height 1.16m, Depth 0.5m Small vertical crack noted on wall face between 2 - 5mm width. Crack on top of wall 10 - 30mm width.	No significant change.	No significant change.	No significant change.	Low	2	Unlikely	2	Low	4	Low

Swanage Town Council - Shore Road - Asset Defect Schedule (February 2026)																	February 2026 Risk Rating	August 2026 Risk Rating					
Defect Ref.	Defect Location	Easting (m)	Northing (m)	Sample Photo of Defect	Initial Defect Description (June 2023)	Defect Description (Oct 2023)	Defect Description (Feb 2024)	Defect Description (May 2024)	Defect Description (October 2024)	Defect Description (February 2025)	Defect Description (June 2025)	Defect Description (October 2025)	Defect Description (February 2026)	Defect Description (August 2026)	Risk Level	Likelihood (Number)	Likelihood	Effect (Number)	Effect	Risk Level (Number)	Risk Level		
C20	Sandpit Field	403057	79147		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A Vertical cracking observed across full height of retaining wall. Cracking in place between blocks where render is no longer present. Mortar debond. No overhang observed. Wall height = 1.6m. Wall Depth = 0.4m. Crack width <10mm.	Crack width <10mm. No significant change.	Crack width <10mm. No significant change.	Low	2	Unlikely	2	Low	4	Low		
C21	Sandpit Field	403058	79166		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A 10m of surface cracking observed in the tarmac pavement within sandpit field. 1 to 2 parallel cracks observed along the whole length. Cracks only in surface of the pavement. Minor subsidence also observed.	No significant change.	No significant change.	Low	1	Negligible	2	Low	2	Low		
C22	Sandpit Field	403008	79295		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A Vertical cracking observed across full height of retaining wall. Cracking in mortar / render. No overhang observed. Wall height = 0.8m. Wall Depth = 0.4m. Crack width <10mm. Low height wall and low risk profile.	No significant change	No significant change	Low	2	Unlikely	2	Low	4	Low		



APPENDIX B – QUALITATIVE RISK ASSESSMENT METHODOLOGY



QUALITATIVE RISK ASSESSMENT (QRA) METHODOLOGY

Qualitative risk assessments are a method of measuring relative risk, based on ranking or descriptive categories. It is an industry standard means of determining a level of risk and is therefore considered appropriate and sufficient for use at this site.

LIKELIHOOD OF FAILURE

The likelihood of failure for each defect shall be assessed with consideration to findings defect and walkover surveys, and results from any previous Ground Investigation Reports.

Table 1 – Qualitative Risk Assessment; Likelihood

Score	Likelihood	Chance of occurrence (%)
5	Almost certain	>70
4	Probable	50-70
3	Likely	30-50
2	Unlikely	10-30
1	Negligible	<10

EFFECT OF FAILURE

The effect should a failure occur within a defect has been considered with reference to:

- Wall or slope geometry;
- Volume of failed material;
- Proximity to roads and pedestrian footways; and
- Potential to cause damage to infrastructure or harm to members of the public, within the site boundary.

Effect is commonly categorised based on the impact to cost or time, including damage to property and personnel injury.

Table 2 - Risk Assessment; Effect

Score	Effect	Cost or Time
4	Very High	Multiple fatalities and/or unserviceable damage to property
3	High	Fatality or injury to people or major damage to property
2	Low	Minor injury to people or minor damage to property
1	Very Low	Negligible damage
0	None	No effect

RISK LEVEL

A Risk Rating can subsequently be calculated using the adopted principle of Risk = Likelihood x Effect. Each risk rating corresponds to the respective Risk Level, ranging from low to very high risk.

Table 3 - Risk Assessment; Risk Level

Score	Risk Level
13-20	Very High
9-12	High
5-8	Medium
0-4	Low